
The **glo-401** replacement hot surface igniter is designed as a direct replacement for the following hot surface igniters.

Amana D99182, B1336102, 10041601

Norton 201A , 271A

Robertshaw Uni-line, 41-401

Trianco Heatmaker 2600-359

White Rogers 767A-356 767A-309